



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Monticello Field Office
P.O. Box 7
Monticello, Utah 84535
<http://www.blm.gov/utah/monticello>



Incoming
\$103.7/0064
CHANTZ

IN REPLY REFER TO:
UTU-68057
(UTY-020)

Dan Shumway
Kiva Drive (5-2)
Blanding, Utah 84511

NOV 19 2009

Re: File Closure, Notice of Intent, Dan Shumway, Lucky/Golden Chantz Mine, UTU-68057 (S0370064), Recapture Canyon, San Juan County, Utah

Dear Mr. Shumway:

On November 12, 2009 personnel from this office performed a close-out inspection at the Lucky/Golden Chantz Mine and found that site reclamation is satisfactory. All equipment and other material have been removed from the site and the oversize rock piles have been graded and covered with topsoil. The pre-existing pipeline road has been re-established through the site. Therefore, you are hereby released from any further reclamation liability and the case file will be retired.

If you have any questions or concerns, please contact Ted McDougall of my staff at (435) 587-1512.

Sincerely,

s/Thomas A. Heinlein

Thomas A. Heinlein
Field Office Manager

cc:
Wayne Western
State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-580

TMcDougall:ses:Golden Chantz Release.ltr 11.17.09

RECEIVED E-Mail
MAY - 3 2010
Div. of Oil, Gas & Mining

E/037/0064



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

P. O. Box 7
Monticello, Utah 84535-0007
(435) 587-1500

File: UTU-68057
Office: (UT-090)

Date: 11/16/09
To: Minerals File UTU-68057
From: Ted McDougall, Geologist
Subject: Surface Management Site Inspection, Dan Shumway, Golden/Lucky Chantz Mine, UTU-68057 (E/037/0064), Recapture Canyon, San Juan County, Utah.

Date of Inspection: 11/12/09
Time of Inspection: 10:00 A.M.
Participants: Ted McDougall
Legal Description: T. 36 S., R. 23 E., Section 18
Mining Claims Involved: Lucky & Golden Chantz
Claimant/Operator: Dan Shumway

The subject mine site is an inactive placer gold operation authorized by BLM in 1991 under regulations at that time which did not require a plan of operations or a bond. The small mine site has been inactive for several years. On June 3, 2009 the BLM and the UDOGM conducted a site inspection and determined that additional reclamation work was required before the site could be released. The BLM and the UDOGM informed the operator of the outstanding reclamation work.

On November 10, 2009 the operator notified the BLM that reclamation was complete. I inspected the site on November 12, 2009 to determine if reclamation was adequate for site release. All of the equipment, including the old trommel, has been removed from the site. The piles of oversize rock have been graded and covered with soil material. The pre-existing pipeline road through the site has been reestablished. The disturbed area is small (roughly 0.25 acre) and the site has a propensity for quick vegetation re-growth because of its location in the canyon bottom. Therefore, I recommend that the site be released without further vegetation monitoring and that the case file be closed.

RECEIVED E-Mail

MAY - 3 2010

Div. of Oil, Gas & Mining



Lucky/Golden Chantz Reclamation. Equipment has been removed from the small site and the site has been graded and topsoiled.



RECEIVED E-Mail

MAY - 3 2010

Div. of Oil, Gas & Mining



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program April 28, 2010

Reviewed:

Mine Name: Golden/Lucky Chance	Permit Number: S/037/0064
Operator Name: Dan Shumway	Inspection Date: April 14, 2010
Inspector(s): T Munson	Time: 4-5 PM
Other Participants: none	Mine Status: regraded

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$0.00

Fees: fees not paid since 2008

Purpose of Inspection: To determine if regrading had been completed and the site cleaned up.

Inspection Summary:

I drove close to the site and had to walk the last hundred yards. The site consists of two piles of regraded dirt approximated 50 by 100 feet in size. The surrounding area is completely overgrown with riparian vegetation and it will be a very short time before these piles are overgrown as well. In conversations with Paul Baker of DOGM and Ted McDougall of the Monticello BLM, it was decided we could release this site and close this permit. The size of the actual disturbance and the area's potential to reclaim itself, dictate this decision, as well as, the relative inaccessibility of this site.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The Division can close this permit with BLM concurrence. No bond exists to return to the operator.

Inspector's Signature


TM:vs

cc: ted_mcdougall@blm.gov


Dan Shumway, 977 East Kiva Drive, Blanding, Ut 84511

O:\M037-SanJuan\S0370064-Golden-LuckyChance\inspections\insp04142010.doc





Regraded pile next to pipeline access road



Regraded pile